

## Current Clamp Adapters

- Provide safe, easy measurement of AC/DC current
- Extend the current measurement capabilities of digital multimeters



Description	Cat. No.
500AAC Clamp Adapter	61-333



Description	Cat. No.
600A AC/DC Clamp Adapter	61-334



Description	Cat. No.
200AAC Clamp Adapter	61-332




Description	Cat. No.
1000AAC Clamp Adapter	61-436



Description	Cat. No.
300AAC Clamp Adapter	61-451

## Flexible Clamp Adapters

- Provide safe, easy measurement of high AC currents
- Large opening and flexible materials to wrap around conductors and bus bars
- Shape Memory allows pre-forming before installation
- Extend the current measurement capabilities of digital multimeters



Description	Cat. No.
1000AAC Flexible Clamp Adapter	61-330
300/3000AAC Flexible Clamp Adapter	61-331

Specifications	61-330	61-331	61-332	61-333	61-334	61-436	61-451
AC Current	1000 A	300/3000 A	200 A	500 A	600 A	1000 A	300 A
DC Current	—	—	—	—	600 A	—	—
Output Signal	1mV/A/10mV/A	1mV/A/10mV/A	1mV/A/10mV/A	1mV/A/10mV/A	1mV/A/10mV/A	1mV/A/10mV/A	1mV/A/10mV/A
Max Conductor Size	8" (19cm)	8" (19cm)	0.78" (19.8mm)	1.18" (30mm)	—	—	—
Sensor Length	24" (61cm)	36" (91cm)	—	—	—	—	—